


IN-LINE INSPECTION SUPPORT FOR 38-MILE 30" GAS PIPELINE

PIPELINE



CHALLENGE

Pipeline operators must comply with current DOT regulations and physically inspect their pipelines on a regular basis. TBS consistently assists with these inspections by providing a variety of solutions.

SOLUTION

TBS performed sub-centimeter level accurate RTK/GPS survey of 36 AGM locations and provided a pig tracking during ILI run through a variety of terrain utilizing all-terrain UTVs, survey boats, airboats, and a marsh buggy.

INTEGRATED SERVICES

- AGM Location Planning and Mapping
- Pig Run Support – AGM Placement, Monitoring, And Pig Tracking
- Pipeline Centerline and Depth of Cover Surveys
- Anomaly Stakeout and Line Marking
- Wetland Permitting for Anomaly Repairs
- As-built Repair Surveys
- Alignment Sheet Preparation and Updates